



Legend

- Vista Point
- Vista Sight Lines
- Well-Established Trail
- Visible Fences from Canyon Bottom
- Visible Structures from Canyon Bottom
- Slope 25-40%
- Slope > 40%
- Erosion
- Stormwater Structure
- Stormwater Conveyance
- Contour Line (2 ft)

Hollywood Canyon | Geotopographic & Viewshed Conditions

Existing Conditions Map Set for Hollywood Canyon



Map Date: 10/20/11 | Imagery Date: Fall 2008
 Data Sources: SanGIS, City of San Diego, San Diego Canyonlands
 Contact: Will Anderson | www.sdcanyonlands.org

